

Supplemental Type Certificate

Number SA4804NM

This Certificate issued to ELT Engineering
14301 Flower Street
Garden Grove, California 92643

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations. *see T.C.D.S. No. 3A15 for complete certification basis

Original Product - Type Certificate Number: 3A15
Make: Beech
Model: see Continuation Sheet No. SA4804NM, page 3

Description of Type Design Change: Installation of replacement storm window hinges and locking device in accordance with FAA sealed E.L.T. Plastic Mold Installation Instructions Report 8965, dated 09/19/89 or later FAA approved revision.

Limitations and Conditions: This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this change and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 24, 1989

Date reissued: March 23, 1992,
February 26, 1996

Date of issuance: November 1, 1989

Date amended:



By direction of the Administrator

Michael A. Murphy
(Signature)

Manager, Technical & Administrative
Support Staff, ANM-103L

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

Supplemental Type Certificate

(Continuation Sheet)

Number SA4804NM

(I) November 1, 1989
(R) March 23, 1992
(R) February 26, 1996

ORIGINAL PRODUCT - MODEL

H35, J35, K35, M35, N35, P35, S35, V35, V35A, V35B, 35-33, 35-A33, 35-B33,
35-C33, 35-C33A, E33, E33A, E33C, F33, F33A, F33C, G33, 36, A36, A36TC,
B36TC

- END -

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.